

# StarFire™ 6000 and StarFire™ 6000 Integrated Receiver

Software Update 20-1 Release Notes

4.30F

---

## Resolved Items:

**AutoTrac™ Kicks out with “No TCM Corrections” Message Received** – Upon engaging AutoTrac™ with a StarFire™ 6000 receiver in a 00/10/20 series tractor, AutoTrac™ disengages after a few seconds with the message “No TCM Corrections”. This software update will resolve this issue.

**Direction Change Displayed Incorrectly in Slow Speed Integrated AutoTrac™** – When traveling at slow speeds (below 0.5 kph/0.3 mph) and changing direction, direction of travel may not display correctly. This software update reduces the minimum speed from 0.5 kph to 0.1 kph for the system to determine correct direction of travel and resolve heading issues.

---

## **Release Notice**

These are software release notes for the StarFire™ 6000 and StarFire™ 6000 Integrated Receiver. Release Notes can be found on [www.stellarsupport.com](http://www.stellarsupport.com). Note: Your use of the software is governed by the End User License Agreement included with the software.

**Copyright © 1996-2020 Deere & Company**