Software Update

Software version 21260002 is the official USB software release. Software 20380002 is still approved for use.

It is recommended to update when able.

The defects fixed or feature added in this release:

- Improvements of Remote-control buttons from command arm related to radio functions
- Bluetooth Hand free speech quality improvements
- Diagnostics improvements related to triggering specific DTCs.
- Diagnostics Address access improvements for the PDU.
- German Language added.
- Fixed issue: radio reboots intermittently when in call and engine cranks
- Fixed issue: preset not saved correctly while scanning or after scanning
- Fixed issue: infrequent loss of audio source volume after power cycle
- Fixed issue: signal strength diagnostic address for DAB reported value in wrong units
- Fixed issue: intermittently on selection DAB preset will switch to previous selected preset value

Standard Face Plate Radio

See images for Radio being referenced as the "Standard Face Plate Radio". This SW update only applies to those radios. These radios began to be built in John Deere machines starting in 2021. If you have a Standard Face Plate Radio and the radio image does not match your radio, you have a radio that does not update via USB and you need to contact your dealer for further information regarding SW updates.

Global DAB Radio:



North America Radio:



Release Notes Content

How To Verify Software Version on Radio Downloading Software from StellarSupport™ Installing Software from USB to Radio Troubleshooting

How To Verify Software Version on Radio

Press and hold the 'SRC' button and wait till the screen goes blank (Clock displayed only).

Then press and hold buttons '1' & '3' together for about 10 sec. (Note: you may have to press the button '1' first and then '3' and hold them both, or if that does not work then press and hold '3' first and then '1' and hold them both.)

The display should come back and tell you 3 lines:

- UNX
- AA1212AA
- Software version

NOTE: If the software version on your radio is not 21260002, the latest software needs to be downloaded from StellarSupport[™]

Downloading Software from StellarSupport[™]

- 1. Select Download under Standard Face Plate Radio on stellarsupport.deere.com
- 2. Save the .zip file onto the USB. For the best results, USB Requirements are:
 - a. Format Windows FAT32
 - b. Capacity 32 GB or smaller is recommended
- 3. Extract the software onto the USB:
 - a. Navigate to the .zip file in USB on File Explorer
 - b. Right click on the .zip file and select 7-zip to choose the option "Extract Here"
 - c. Contents of zip folder must be on root level of the USB drive. Not in a folder
- 4. USB Drive Letter (D:\ etc) should look like this

config.conf	7/1/2021 1:45 PM	CONF File	66 KB
target00001.tgt	7/1/2021 1:43 PM	TGT File	6,274 KB
target00002.tgt	7/1/2021 1:43 PM	TGT File	5,122 KB
target00003.tgt	7/1/2021 1:43 PM	TGT File	514 KB
target00004.tgt	7/1/2021 1:43 PM	TGT File	66 KB
target00005.tgt	7/1/2021 1:43 PM	TGT File	66 KB
target00006.tgt	7/1/2021 1:44 PM	TGT File	66 KB
target00007.tgt	7/1/2021 1:44 PM	TGT File	3,586 KB
target00008.tgt	7/1/2021 1:44 PM	TGT File	130 KB
target00009.tgt	7/1/2021 1:44 PM	TGT File	5,762 KB
target00010.tgt	7/1/2021 1:44 PM	TGT File	15,810 KB
target00011.tgt	7/1/2021 1:44 PM	TGT File	9,922 KB
target00012.tgt	7/1/2021 1:44 PM	TGT File	66 KB
target00013.tgt	7/1/2021 1:44 PM	TGT File	66 KB

Installing Software from USB to Radio

1. Insert the USB into the USB port for the radio (AUX/USB connector)



- 2. Wait until the radio has found the USB drive and displays "no music" or play music from USB. (1-2 minutes)
- 3. Press and hold the 'SRC' button and wait till the screen goes blank (Clock displayed only)
- 4. Now press and hold the preset buttons '3' and '6' together and wait for about 10-15sec.
 - The Radio will start the reprogramming sequence. (Note: you may have to press the button '3' first and then '6' and hold them both, or if that does not work then press and hold '6' first and then '3' and hold them both.)
- 5. Leave USB in until programming is complete. Radio will tell you when programming is complete on the screen. (Radio will be turning itself off/on during the programming process)
- 6. Once installed, do an additional key cycle of the vehicle to complete the installation process.

Note: If a USB error screen appears, leave USB connected and wait for radio to revert to normal state. This process will take a few minutes. Then refer to <u>Troubleshooting</u> for additional details.

Troubleshooting

If the screen "USB Error" appears or another failure of software installation occurs, these are recommended troubleshooting steps:

- Verify you have downloaded the right software version for your country or region. Go to <u>stellarsupport.deere.com</u> and select your country to download the correct software. If your country is not listed, select a nearby country with your desired language or an International page.
- Verify USB format is correct. Recommended formatting is FAT32.
- Verify USB size is not too large. Recommended USB size is 32GB or smaller.
- Try another USB brand. Different or older USB brands can format USBs differently and may not be compatible.
- Try to download the USB files again from StellarSupport[™]. The download process can corrupt a file due to download errors.
- Try downloading the software using a different web browser.
- Attempt an additional key cycle if software does not seem to work after programming with USB.
- If XOB error is reported, try the steps on <u>USB Re-formatting</u>.

USB Re-formatting

Sometime when programming the radio will report an XOB error, and that may mean you have to reformat your USB. Below are the 3 options for reformatting:

- Quick Format
- Full Format
- Diskpart clean

Quick format will delete partition data. Quick format is overwriting the information in a partition. A Full format scans for bad sectors of a partition and overwrite data. (but there could still be hidden partitions or bad

data).

Diskpart clean should erase a partition and clear the whole drive.

1) Quick Format: (This is the fastest way to format)

Right click on USB drive from File explorer. Confirm "Quick Format" box is checked and click Start.

Format USB Drive (E:)	>
Capacity:	
7.26 GB	~
File system	
FAT32 (Default)	~
Allocation unit size	
16 kilobytes	~
Volume label	
Format options	
Quick Format	
Start	Close

2) Full Format: (this will take more time to format, meaning you will have to wait multiple minutes) Right click on USB drive from File explorer. Confirm "Quick Format" box is NOT checked and click Start.

Format USB Drive (E:)	×
Capacity:	
7.26 GB	~
File system	
FAT32 (Default)	~
Allocation unit size	
16 kilobytes	~
Restore device defaults	
Volume label	
Volume label	

3) Diskpart clean: (erases the partition on the USB)

(Search "Diskpart clean" on a video website for helpful video walkthroughs.)

Open Command Prompt from Start menu:



Type "diskpart" and hit enter. (it may open up another window or it may use same window)



Type "list disk" and hit enter

000010 0	iskPart versi	on 10.0.177	63.1		
opyright (computer	C) Microsoft :	Corporation			
SKPART> 1	ist disk				
Disk ###	Status	Size	Free	Dyn	Gpt
	Online	931 GB	1024 KB		*
Disk 0	OUTTUE				
Disk 0 Disk 1	Online	476 GB	47 GB		*

Locate the USB drive. I have an 8Gb connected and so I know the USB is Disk 2 in the list. You now need to select your disk. In my instance it is disk 2.

Type "select disk 2" and hit enter

```
C:\WINDOWS\System32\diskpart.exe
```

```
Microsoft DiskPart version 10.0.17763.1
Copyright (C) Microsoft Corporation.
On computer:
DISKPART> list disk
 Disk ###
           Status
                          Size
                                   Free
                                            Dyn
                                                 Gpt
           Disk 0
           Online
                           931 GB
                                   1024 KB
 Disk 1
           Online
                           476 GB
                                     47 GB
                                                   ×.
 Disk 2
           Online
                          7437 MB
                                       0 B
DISKPART> select disk 2
Disk 2 is now the selected disk.
DISKPART>
```

Type "clean" and hit enter. This will erase and remove all data on the USB. You will then have 8Gb of unallocated space on the USB.



Open Computer Management from Start menu. Under Storage on the list, select Disk Management

 Computer Management (Local) System Tools Task Scheduler Event Viewer 	Volume	Layout	Type F	ile System	Status		Actions
				ITFS (BitLocker Encrypted		, Page File, Crash Dump, Primary I	Disk Manage
	 (Disk 1 partition 2) New Volume (D:) 	Simple I Simple I		ITES	Healthy (EFI S Healthy (Prim	ystem Partition) any Partition)	More Ad
> al Shared Folders	- Windows RE Tools				Healthy (Prim		
> 🖉 Local Users and Groups	1.01						
> (S) Performance Device Manager							
✓ Manager							
- Disk Management							
> Bervices and Applications							
5							
	<					>	
	Basic	ew Volum	a (Du)				
	931.50 GB g	31.50 GB N	TFS				
	Online H	lealthy (Prin	mary Par	rtition)			
	= Disk 1						
		Vindows R	512 N	(C:)	S (BitLocker Enc	47.60 GB	
		lealthy (Pri			Page File, Crash	Unallocated	
				///////////////////////////////////////			
			J				
						1	
	- Disk 2 Removable (E:)			<u>Killin</u>	(1	

Right Click on the unallocated space, Select "New Simple Volume"

×



A wizard should appear.

New Simple Volume Wizard



11

You should be able to hit Next and select all the default options already selected. Make sure to select FAT32 for file system for best results

Format Partition			
To store data on this partition, yo	u must format it first.		
Choose whether you want to for	nat this volume, and if s	o, what settings you wa	nt to use.
O Do not format this volume			
Format this volume with the second	e following settings:		
File system:	FAT32	~	
Allocation unit size:	Default	~	
Volume label:	New Volume		
Perform a quick form	nat		
Enable file and folde	r compression		

When it is Finished, you should have a formatted a clean USB

Release Notice

These are software update release notes for the standard face plate radio available in certain John Deere machines.Release notes can be found on <u>www.stellarsupport.com</u>. Note: Your use of the software is governed by the End User License Agreement included with the software.

Copyright © 1996-2021 Deere & Company